Attachment 12 Reporting Form - Construction Activities Village of Castleton-on-Hudson

Property Owner	Address	Inspection By	Dates	Comments	Action
Richard Nunziato	11 Park Way	Clark Engineering & Surveying, P.C./ Doug	2004	Sope & erosion control issues for new construction	Erosion control measures established, foundation drains installed,
		Clark, Derrick Gardner		of residence.	silt fence, haybales, seed & mulch.
1 Benedict Street	1 Benedict Street	Clark Engineering & Surveying, P.C./ Doug		Fill material being placed at top of slopedrains	Drains rerouted. Brush removed from embankment, stumps left in
		Clark, Derrick Gardner	7/31/06, 2/30/07	outlet on slope. Tree Clearing on slope.	place. Silt fence & seeding.
Daniel O'Neill	77 Scott Avenue	Clark Engineering & Surveying,	9/14/06, 1/27/07	Brush & debris causing erosion, sedimentation of	Brush & debris removed from slope. Slope regraded. Slt fence,
		P.C./ Derrick Gardner		catch basin.	seed and mulch installed.
Donald Walsh	9 Hillview Terrace	Clark Engineering & Surveying, P.C./Doug	2005/2007	Tree clearing along steep slope requested in front	Plan submitted and initial approval. No construction started yet.
		Clark, Derrick Gardner		of planning board.	
KSR Holding, LLC	Seaman Avenue	Clark Engineering & Surveying, P.C./Doug	2006/2007	8-Lot subdivision review.	Stormwater plan approved by planning board with review by Clark
		Clark, Derrick Gardner			Engineering & Surveying, P.C.
Village of Castleton-on-	n- Scott Avenue	Clark Engineering & Surveying,	2006/2007	Sidewalk, curbing, shoulder, & catch basin	Silt fence, haybales, seed & mulch implemented. Full time
Hudson		P.C./Derrick Gardner, Kyle Gardner		replacement along portion of Scott Avenue.	inspection by Clark Engineering & Surveying, P.C.
Resurrection Nursing	Route 9J	Clark Engineering & Surveying,	2/2/2007	Fill material and grading taking place.	Less then 1/2 acre of disturbance, no erosion issues, no further
Home		P.C./Derrick Gardner			action.
Schodack Central	Scott Avenue	Clark Engineering & Surveying, P.C./ Doug	2007/2008	Elementary school improvements. Stormwater	SWPP reviewed and some inspection of work completed.
School		Clark, Derrick Gardner		control plans set up.	
Doug Porter	29 Prins Hill Way	Clark Engineering & Surveying,	4/23/08, 6/5/08,	Tree clearing & disturbance along steep slope.	Stop work ordered. Plan submitted by owner to planning board.
		P.C./Derrick Gardner	10/22/08	Erosion control concerns.	Plantings & erosion control measures implemented.
Joseph Scandura	110 Green	Clark Engineering & Surveying,	2008	Initial submission of subdivision plans.	Recommendations made for site plan submission. No further action
	Avenue	P.C./ Derrick Gardner	2000		by owner.
Village of Castleton-on-	Green Avenue &	Clark Engineering & Surveying,	2008/2009	Road reconstruction, including; water, stormwater,	Silt fence, haybales, seed & mulch implemented. Full time
Hudson	2nd Street	P.C./ Derrick Gardner, Kyle Gardner	2000/2003	sidewalks, curbing, & pavement.	inspection by Clark Engineering & Surveying, P.C.